

CERTIFICATE OF COMPLIANCE

Certificate Number 20180206-EX16385
Report Reference EX16385-20180205
Issue Date 2018-FEBRUARY-06

Issued to: DUYAR VANA MAKINA SAN VE TIC A S
Osmangazi Mh. 2653 Sk. No:7
34522 Esenyurt Istanbul TURKEY


This is to certify that representative samples of VALVES, ALARM
See Addendum Page

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 193 : Alarm Valves for Fire-Protection Service
Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20180206-EX16385
Report Reference EX16385-20180205
Issue Date 2018-FEBRUARY-06


This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Model*	Nominal Pipe Size, NPS	End Configuration	Rated Pressure, psig	Installation Position
Y-4010	6	F by F	300	V

F – Flanged

V – Vertical installation

*Note – The valves are provided with a pressure switch for only electrical alarm.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

